

# A Guide to

# Worksite Fire Safety

*Help prevent fires at your worksite by following these guidelines:*

## **ALWAYS...**

- Keep equipment and machinery clean and in good operating condition.
- Make sure that all electrical equipment is protected.
- Store flammable or combustible materials in the right containers away from heat sources.




*• Keep work areas clean and free of debris.*



- Dispose of flammables according to established safety guidelines.
- Use caution when operating welding and other spark-producing equipment.
- Clean or report all spills.
- **Report suspicious persons to security or plant manager.**
- Keep fire exits and escape routes clear and well marked.
- Know where alarm boxes are located.


## **NEVER...**

- Never leave open flames unattended.
- Never overload circuits.
- Never take shortcuts with safety procedures.
- **Never smoke or use flame or sparks in an area where flammables are present.**



## **Common Worksite Fire Hazards**

- Unprotected or faulty equipment
- **Unsafe storage of combustible materials**
- Inadequate ventilation
- Failure to follow established safety guidelines
- Inattention
- Human error



**FIRE SAFETY & EMERGENCY RESPONSE**