

Priority Areas Lead Testing and Corrective Actions NOVEMBER 2014  
NAS Key West Child Development Center Building V-4187

Table 1. Summary of Results

SAMPLING LOCATION DESCRIPTION			INITIAL SAMPLING RESULTS			RE-SAMPLING RESULTS			CORRECTIVE ACTIONS	POST REMEDIATION SAMPLING RESULTS			
			CATEGORY Water Intended For:	SAMPLE ID	Outlet Description	First Draw (ppb)	Retest required?	Date Fixture Secured?		Recommended Level = 20ppb			First Draw (ppb)
Water Fountain 15 min. Follow up Flush Sample - Collected day before First Draw Sampling (ppb)	First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)							First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)			
<b>SAMPLING DATE</b>			11/4/2014			mm/dd/yyyy	mm/dd/yyy y	mm/dd/yyyy				mm/dd/yyyy	
<b>RESULTS DATE</b>			11/12/2014			mm/dd/yyyy	mm/dd/yyy y	mm/dd/yyyy				mm/dd/yyyy	
DRINKING	KW-V4187-LOBBY-WFC-A-FD (BLDG 4187-2)	Outside lobby restroom - Dual water fountains in lobby near restroom	non-detect	NO	N/A	N/A	N/A	N/A				N/A	N/A
DRINKING	KW-V4187-LOBBY-WFC-B-FD (BLDG 4187-3)	Outside lobby restroom - Dual water fountains in lobby near restroom	non-detect	NO	N/A	N/A	N/A	N/A				N/A	N/A
COOKING/TEETHBRUSHING	KW-V4187-RM133-RM-TB-A-FD (BLDG 4187-14)	Pre-toddler Room 1 - Low, single faucet open sink in classroom used for teethbrushing.	1.4	NO	N/A	N/A	N/A	N/A				N/A	N/A
COOKING/TEETHBRUSHING	KW-V4187-RM130-RM-TB-FD (BLDG 4187-15)	Pre-toddler Room 2 - Low, single faucet open sink in classroom used for teethbrushing.	1.2	NO	N/A	N/A	N/A	N/A				N/A	N/A
COOKING/TEETHBRUSHING	KW-V4187-RM128-RM-TB-A-FD (BLDG 4187-22)	Pre-toddler Room 3 - Low, single faucet open sink in classroom used for teethbrushing.	2.9	NO	N/A	N/A	N/A	N/A				N/A	N/A
COOKING/TEETHBRUSHING	KW-V4187-RM125-RM-TB-FD (BLDG 4187-23)	Pre-toddler Room 4 - Low, single faucet open sink in classroom used for teethbrushing.	non-detect	NO	N/A	N/A	N/A	N/A				N/A	N/A
COOKING/TEETHBRUSHING	KW-V4187-RM119-RM-TB-FD (BLDG 4187-31)	Toddler Room 1 - Low, single faucet open sink in classroom used for teethbrushing.	non-detect	NO	N/A	N/A	N/A	N/A				N/A	N/A
COOKING/TEETHBRUSHING	KW-V4187-RM116-RM-TB-FD (BLDG 4187-32)	Toddler Room 2 - Low, single faucet open sink in classroom used for teethbrushing.	non-detect	NO	N/A	N/A	N/A	N/A				N/A	N/A
COOKING/TEETHBRUSHING	KW-V4187-RM114-RM-TB-FD (BLDG 4187-40)	Pre-school Room 1 - Low, single faucet open sink in classroom used for teethbrushing.	non-detect	NO	N/A	N/A	N/A	N/A				N/A	N/A

Priority Areas Lead Testing and Corrective Actions NOVEMBER 2014  
NAS Key West Child Development Center Building V-4187

SAMPLING LOCATION DESCRIPTION			INITIAL SAMPLING RESULTS			RE-SAMPLING RESULTS			CORRECTIVE ACTIONS	POST REMEDIATION SAMPLING RESULTS	
			CATEGORY Water Intended For:	SAMPLE ID	Outlet Description	First Draw (ppb)	Retest required?	Date Fixture Secured?		Recommended Level = 20ppb	
Water Fountain 15 min. Follow up Flush Sample - Collected day before First Draw Sampling (ppb)	First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)							Description	First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)
<b>SAMPLING DATE</b>			11/4/2014			mm/dd/yyyy	mm/dd/yyyy	mm/dd/yyyy		mm/dd/yyyy	
<b>RESULTS DATE</b>			11/12/2014			mm/dd/yyyy	mm/dd/yyyy	mm/dd/yyyy		mm/dd/yyyy	
COOKING/TEETHBRUSHING	KW-V4187-RM105-RM-TB-FD (BLDG 4187-50)	Pre-school Room 2 - Low, single faucet open sink in classroom used for teethbrushing.	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
COOKING/TEETHBRUSHING	KW-V4187-RM102-RM-TB-FD (BLDG 4187-51)	Pre-school Room 3 - Low, single faucet open sink in classroom used for teethbrushing.	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
COOKING	KW-V4187-RM142-LOUNGE-K FD (BLDG 4187-4)	Teachers Lounge - Kitchen sink on right side of room in lounge	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
COOKING	KW-V4187-RM108-K-K-A-FD (BLDG 4187-42)	Kitchen - First faucet on double sink used for dishes and filling water coolers.	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
COOKING	KW-V4187-RM108-K-K-B-FD (BLDG 4187-43)	Kitchen - Second faucet on double sink used for dishes and filling water coolers.	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
COOKING	KW-V4187-RM108-K-K-C-FD (BLDG 4187-44)	Kitchen - Small center island food prep sink.	20	NO	N/A	N/A	N/A	N/A		N/A	N/A
COOKING	KW-V4187-RM108-K-HHW-FD (BLDG 4187-46)	Kitchen - Hand washing sink on middle of right side of kitchen	1.7	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	KW-V4187-LOBBY-BATH-HHW- FD (BLDG 4187-1)	Lobby restroom - Combined restroom in CDC Lobby	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	KW-V4187-RM141-RM-HHW- A-FD (BLDG 4187-5)	Infant Room 1 - Double stainless steel sink in shared changing area.	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	KW-V4187-RM141-RM-HHW- B-FD (BLDG 4187-6)	Infant Room 1 - Single stainless steel sink on Rm 139 side of shared changing area	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	KW-V4187-RM141-RM-HHW- C-FD (BLDG 4187-7)	Infant Room 1 - Single stainless steel sink on Rm 141 side of shared changing area	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A

Priority Areas Lead Testing and Corrective Actions NOVEMBER 2014  
NAS Key West Child Development Center Building V-4187

SAMPLING LOCATION DESCRIPTION			INITIAL SAMPLING RESULTS			RE-SAMPLING RESULTS			CORRECTIVE ACTIONS	POST REMEDIATION SAMPLING RESULTS	
			CATEGORY Water Intended For:	SAMPLE ID	Outlet Description	First Draw (ppb)	Retest required?	Date Fixture Secured?		Recommended Level = 20ppb	
Water Fountain 15 min. Follow up Flush Sample - Collected day before First Draw Sampling (ppb)	First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)							Description	First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)
<b>SAMPLING DATE</b>			11/4/2014			mm/dd/yyyy	mm/dd/yyyy	mm/dd/yyyy		mm/dd/yyyy	
<b>RESULTS DATE</b>			11/12/2014			mm/dd/yyyy	mm/dd/yyyy	mm/dd/yyyy		mm/dd/yyyy	
WASHING	KW-V4187-RM138-RM-HHW-A-FD (BLDG 4187-8)	Infant Room 2 - Double stainless steel sink in shared changing area.	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	KW-V4187-RM138-RM-HHW-B-FD (BLDG 4187-9)	Infant Room 2 - Single stainless steel sink on Rm 136 side of shared changing area	4.2	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	KW-V4187-RM138-RM-HHW-C-FD (BLDG 4187-10)	Infant Room 2 - Single stainless steel sink on Rm 138 side of shared changing area	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	KW-V4187-RM133-RM-HHW-A-FD (BLDG 4187-11)	Pre-toddler Room 1 - Single stainless steel sink on Rm 133 side of shared changing area	6.8	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	KW-V4187-RM133-RM-HHW-B-FD (BLDG 4187-12)	Pre-toddler Room 1 - Stainless steel sink outside changing area and child's bathroom.	1.6	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	KW-V4187-RM133-RM-LHW-FD (BLDG 4187-13)	Pre-toddler Room 1 - Child's bathroom sink	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	KW-V4187-RM130-RM-LHW-FD (BLDG 4187-16)	Pre-toddler Room 2 - Child's bathroom sink	3.7	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	KW-V4187-RM130-RM-HHW-A-FD (BLDG 4187-17)	Pre-toddler Room 2 - Stainless steel sink outside changing area and child's bathroom.	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	KW-V4187-RM130-RM-HHW-B-FD (BLDG 4187-18)	Pre-toddler Room 2 - Single stainless steel sink on Rm 130 side of shared changing area	2.3	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	KW-V4187-RM128-RM-HHW-A-FD (BLDG 4187-19)	Pre-toddler Room 3 - Single stainless steel sink on Rm 128 side of shared changing area	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A

Priority Areas Lead Testing and Corrective Actions NOVEMBER 2014  
NAS Key West Child Development Center Building V-4187

SAMPLING LOCATION DESCRIPTION			INITIAL SAMPLING RESULTS			RE-SAMPLING RESULTS			CORRECTIVE ACTIONS	POST REMEDIATION SAMPLING RESULTS	
			CATEGORY Water Intended For:	SAMPLE ID	Outlet Description	First Draw (ppb)	Retest required?	Date Fixture Secured?		Recommended Level = 20ppb	
Water Fountain 15 min. Follow up Flush Sample - Collected day before First Draw Sampling (ppb)	First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)							Description	First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)
<b>SAMPLING DATE</b>			<b>11/4/2014</b>			<b>mm/dd/yyyy</b>	<b>mm/dd/yyyy</b>	<b>mm/dd/yyyy</b>		<b>mm/dd/yyyy</b>	
<b>RESULTS DATE</b>			<b>11/12/2014</b>			<b>mm/dd/yyyy</b>	<b>mm/dd/yyyy</b>	<b>mm/dd/yyyy</b>		<b>mm/dd/yyyy</b>	
WASHING	KW-V4187-RM128-RM-HHW-B-FD (BLDG 4187-20)	Pre-toddler Room 3 - Stainless steel sink outside changing area and child's bathroom.	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	KW-V4187-RM128-RM-LHW-FD (BLDG 4187-21)	Pre-toddler Room 3 - Child's bathroom sink	1.3	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	KW-V4187-RM125-RM-LHW-FD (BLDG 4187-24)	Pre-toddler Room 4 - Child's bathroom sink	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	KW-V4187-RM125-RM-HHW-A-FD (BLDG 4187-25)	Pre-toddler Room 4 - Stainless steel sink outside changing area and child's bathroom.	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	KW-V4187-RM125-RM-HHW-B-FD (BLDG 4187-26)	Pre-toddler Room 4 - Single stainless steel sink on Rm 125 side of shared changing area	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	KW-V4187-RM119-RM-HHW-A-FD (BLDG 4187-27)	Toddler Room 1 - Single stainless steel sink on Rm 119 side of shared area	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	KW-V4187-RM119-RM-LHW-A-FD (BLDG 4187-28)	Toddler Room 1 - Child's bathroom sink	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	KW-V4187-RM119-RM-LHW-B-FD (BLDG 4187-29)	Toddler Room 1 - Child's bathroom sink	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	KW-V4187-RM119-RM-HHW-B-FD (BLDG 4187-30)	Toddler Room 1 - Stainless steel sink outside shared area and child's bathroom.	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	KW-V4187-RM116-RM-LHW-A-FD (BLDG 4187-33)	Toddler Room 2 - Child's bathroom sink	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	KW-V4187-RM116-RM-LHW-B-FD (BLDG 4187-34)	Toddler Room 2 - Child's bathroom sink	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	KW-V4187-RM116-RM-HHW-A-FD (BLDG 4187-35)	Toddler Room 2 - Stainless steel sink outside shared area and child's bathroom.	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	KW-V4187-RM116-RM-HHW-B-FD (BLDG 4187-36)	Toddler Room 2 - Single stainless steel sink on Rm 116 side of shared area	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	KW-V4187-RM114-RM-LHW-A-FD (BLDG 4187-37)	Pre-school Room 1 - Child's bathroom sink	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A

Priority Areas Lead Testing and Corrective Actions NOVEMBER 2014  
NAS Key West Child Development Center Building V-4187

SAMPLING LOCATION DESCRIPTION			INITIAL SAMPLING RESULTS			RE-SAMPLING RESULTS			CORRECTIVE ACTIONS	POST REMEDIATION SAMPLING RESULTS	
			CATEGORY Water Intended For:	SAMPLE ID	Outlet Description	First Draw (ppb)	Retest required?	Date Fixture Secured?		Recommended Level = 20ppb	
Water Fountain 15 min. Follow up Flush Sample - Collected day before First Draw Sampling (ppb)	First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)							Description	First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)
<b>SAMPLING DATE</b>			<b>11/4/2014</b>			<b>mm/dd/yyyy</b>	<b>mm/dd/yyyy</b>	<b>mm/dd/yyyy</b>		<b>mm/dd/yyyy</b>	
<b>RESULTS DATE</b>			<b>11/12/2014</b>			<b>mm/dd/yyyy</b>	<b>mm/dd/yyyy</b>	<b>mm/dd/yyyy</b>		<b>mm/dd/yyyy</b>	
WASHING	KW-V4187-RM114-RM-LHW-B-FD (BLDG 4187-38)	Pre-school Room 1 - Child's bathroom sink	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	KW-V4187-RM114-RM-HHW-FD (BLDG 4187-39)	Pre-school Room 1 - Stainless steel sink outside child's bathroom.	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	KW-V4187-RM111-RM-HHW-FD (BLDG 4187-41)	Training Room - Stainless steel sink	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	KW-V4187-RM105-RM-HHW-FD (BLDG 4187-47)	Pre-school Room 2 - Near door to the room.	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	KW-V4187-RM105-RM-LHW-A-FD (BLDG 4187-48)	Pre-school Room 2 - Boys bathroom sink.	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	KW-V4187-RM105-RM-LHW-B-FD (BLDG 4187-49)	Pre-school Room 2 - Girls bathroom sink.	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	KW-V4187-RM102-RM-LHW-A-FD (BLDG 4187-52)	Pre-school Room 3 - Boys bathroom sink.	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	KW-V4187-RM102-RM-LHW-B-FD (BLDG 4187-53)	Pre-school Room 3 - Girls bathroom sink.	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	KW-V4187-RM102-RM-HHW-FD (BLDG 4187-54)	Pre-school Room 3 - Near door to the room.	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A

Notes:

Priority Areas Lead Testing and Corrective Actions NOVEMBER 2014  
 NAS Key West Child Development Center Building V-4187

Table 2. Summary Statistics

CATEGORY	INITIAL SAMPLING RESULTS	RE-SAMPLING RESULTS			POST REMEDIATION RESULTS
	Recommended Level = 20ppb				
	First Draw (ppb)	Water Fountain	First Draw (ppb)	Follow up Flush	First Draw (ppb)
Total Drinking	2	0	0	0	0
Total Drinking > 20 ppb	0	0	0	0	0
Total Cook/Brush	14	0	0	0	0
Total Cook/Brush > 20 ppb	0	0	0	0	0
Total Washing	37	0	0	0	0
Total Washing > 20 ppb	0	0	0	0	0
Total Samples	53	0	0	0	0
Total Samples > 20 ppb	0	0	0	0	0