

Priority Areas Lead Testing and Corrective Actions NOVEMBER 2014  
 NAS JACKSONVILLE Gym  
 Building 2066

Table 1. Summary of Results

SAMPLING LOCATION DESCRIPTION			INITIAL SAMPLING RESULTS			RE-SAMPLING RESULTS			CORRECTIVE ACTIONS	POST REMEDIATION SAMPLING RESULTS	
			CATEGORY Water Intended For:	SAMPLE ID	Outlet Description	First Draw (ppb)	Retest required?	Date Fixture Secured?		Recommended Level = 20ppb	
Water Fountain 15 min. Follow up Flush Sample - Collected day before First Draw Sampling (ppb)	First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)							First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)	
<b>SAMPLING DATE</b>			<b>10/11/2014</b>			<b>mm/dd/yyyy</b>	<b>mm/dd/yyyy</b>	<b>mm/dd/yyyy</b>		<b>mm/dd/yyyy</b>	
<b>RESULTS DATE</b>			<b>10/26/2014</b>			<b>mm/dd/yyyy</b>	<b>mm/dd/yyyy</b>	<b>mm/dd/yyyy</b>		<b>mm/dd/yyyy</b>	
DRINKING	JAX-2069-HALL-WFCA-FD (BLDG 2069-1)	Fountain In Lobby High, on left	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
DRINKING	JAX-2069-HALL-WFCB-FD (BLDG 2069 -2)	Fountain In Lobby Low, on right	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
COOKING	JAX 2069-K-K-FD (BLDG 2069-6)	Kitchen sink behind front desk - Break room	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	JAX-2069-BATHW-HHW-FD (BLDG 2069-3)	Lobby Rest Room Women Restroom sink	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	JAX-2069-BATHM-HHW-FD (BLDG 2069-4)	Lobby Rest Room Men Restroom sink	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	JAX-2069-BATH-M/W-HHW- FD (BLDG 2069-5)	Lobby - rest room sink across from front desk	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	JAX-2069-RM1-RM-HHW-FD (BLDG 2069-7)	First room on right Education, yellow room	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	JAX-2069-RM2-RM-HHW-FD (BLDG 2069-8)	Second room on right Art, blue room	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	JAX-2069-RM3-RM-HHW-FD (BLDG 2069-9)	Third room on right Science, Green room	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	JAX-2069-RM4-RM-HHW-FD (BLDG 2069-10)	First room on left Dramatic Play, teal room	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	JAX-2069-RM5-RM-HHW-FD (BLDG 2069-11)	Second room on left Manipulative, orange room	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A

Notes:

Priority Areas Lead Testing and Corrective Actions NOVEMBER 2014  
 NAS JACKSONVILLE Gym  
 Building 2066

Table 2. Summary Statistics

CATEGORY	INITIAL SAMPLING RESULTS	RE-SAMPLING RESULTS			POST REMEDIATION RESULTS
	Recommended Level = 20ppb				
	First Draw (ppb)	Water Fountain Follow up Flush Sample - Collected day before First Draw Sampling (ppb)	First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)	First Draw (ppb)
Total Drinking	2	0	0	0	0
Total Drinking > 20 ppb	0	0	0	0	0
Total Cook/Brush	1	0	0	0	0
Total Cook/Brush > 20 ppb	0	0	0	0	0
Total Washing	8	0	0	0	0
Total Washing > 20 ppb	0	0	0	0	0
Total Samples	11	0	0	0	0
Total Samples > 20 ppb	0	0	0	0	0